Page 1

July 10, 2009 11:21:41 AM

Item ID:

D2221

Revision ID: Н

Item Name:

350 Basket Base

Start Date:

7/15/09

Required Date: 7/27/09

Start Qty: 1.00 Req'd Qty: 1.00



Accept

Setup Start



Stop

Reference:

Approvals:

Process Plan:

QC:

Date:

Date:

Tooling:

SPC (Y/N):

0.00

0.00

Date:

Date:

Run Start

Stop

Sequence ID/ Work Center ID

Operation Description Set Up/ **Run Hours** Draw Number

Cust Item ID:

Customer:

Plan Draw Rev. Code

Reject Accept Qty Qty

Reject Number

Insp. Stamp

Draw Nbr

Revision Nbr

D2221

Rev H

100

Large Fab Large Fab

Large Fab

Memo

1- assemble all ribs and both D2581 in DT9444 jig, weld as per dwg D2221 🗆 2remove basket from jig and weld D3442-1 shims and D2232-3 hinges as per dwg D2221 3- tack weld mesh on basket as per dwg D2221 A/R ER316

S.S. Rod Batch: <u>MID 9213</u>

Malo4/21

110

QC

Quality Control

QC9- Inspect visual per QS1004- Fusion Welds

QC6- Inspect dimensions to drawing ---

0.00

Memo

0.00

120

QC

Memo

Sorlasor

Quality Control

D2221

Н **Revision ID:**

Item Name:

350 Basket Base

Start Date:

7/15/09

Start Qty: 1.00

Required Date: 7/27/09

Req'd Qty: 1.00

Accept

Setup Start

Stop

Reference:

Approvals:

Process Plan:

QC:

Date: _____ Date:

Tooling:

SPC (Y/N):

Date:

Cust Item ID:

Customer:

Draw

Date:

Draw

Rev.

Plan

Code

Run

Start



Stop

Reject

Oty

Sequence ID/ Work Center ID


130

Powdercoat

Powder Coating

Operation Description

White Gloss(Ref:4.3.5.1) per QSI005 4.3-Alum



Set Up/

Number **Run Hours**

-07-22 START 11:30 TEMP 400° FINISH 12:00

Accept

Oty

140 QC3- Inspect Part Finish

0.00

)509/alo3

OC

Quality Control

150

QC21- Final Inspection - Work Order Release

0.00

Memo

Memo

0.00

U S. St. 28

Page 2

Number Stamp

Reject Insp.

QC

Quality Control

July 10, 2009 11:21:41 AM

Work Order ID: 50195

Parent Item:

D2221RevH

Parent Item Name: 350 Basket Base



Start Date: 7/15/09

Required Date: 7/27/09

Comments:								\$	Start Qty: 1.00)	Required Qty:	1.00
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D2221-1RevH		Manufactured	No	· · ·		100	Each	13.0000	1.0000			
				<u>Wareho</u>	use	Loc	Oty	Loc Code				
					ation_							
				Main Wa	arehouse							
				ST	48101		13		_			
					48318		1 4		<u></u>	1 x	lu a	9/07/16
					48427		8		_		- 1000	9 10 7 110
D2221-5RevH		Manufactured	No			100	Each	2.0000	2.0000			
NO.				Wareho Loca		-	<u>Oty</u>	Loc Code			2 1	
				Main Wa ST		B 50	026		<i>(</i>	λ _γ	Syc	×104/16
D2221-7RevH		MC	No		48390	100	2 Each	5.0000	1.0000			
		Manufactured	NO			100	Each	3.0000	1.0000			
Kib				Wareho	use	Loc	<u>Oty</u>	Loc Code				
				Loca	ation							
				Main Wa	arehouse							
				ST			5		_			
					48201 48450		1 4			1 x	·	09/04/16
							•					ノイノひ 午 1 1 6

July 10, 2009 11:21:41 AM

Work Order ID: 50195

Parent Item:

D2221RevH

Parent Item Name: 350 Basket Base

Comments:



Start Date: 7/15/09

Required Date: 7/27/09

Start Qty: 1.00

Required Qty: 1.00

24 Sy 09/04/16

Tax Sy 09 104/16

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D2232-3RevC		Manufactured	No			100	Each	13.0000	2.0000			

Basket Hinge

Warehouse	<u>Lo</u>	c Oty	Loc Code	
Location				
Main Warehouse				
ST		13		
47263		1		
48443		12		
	100	Each	15.0000	2.0000

D2235-1RevB1

Manufactured

No



D 14 D 11	

Basket Rib

Warehouse	Lo	c Oty	Loc Code		
Location					
Main Warehouse					
ST		15			
48665		5			
50029		10			
	100	Each	33.0000	2.0000	

D2581RevA1

Mounting Bracket

Manufactured No

Loc Code

<u>Warehouse</u>	Loc Qty
Location	
Main Warehouse	
ST	33
46086	2
48428	31

D 09 107/16

July 10, 2009 11:21:41 AM

Work Order ID: 50195

Parent Item:

D2221RevH

Parent Item Name:

350 Basket Base

Comments:



No

No

Manufactured

Start Date: 7/15/09

Required Date: 7/27/09

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/	Replacement	Mfg/	Bin	Primary	Last	Route	Unit of	Qty on	Remaining	Qty	Date	Status
Item Name	Item ID	Purch	Item	Location	Location	Seq ID	Measure	Hand	Qty To Pick	Issued	Issued	
D3442-1RevA		Manufactured	No			100	Each	20.0000	2.0000			

Shim

<u>Warehouse</u>	Lo	c Oty	Loc Code			
Location						
Main Warehouse						
ST		20				
46767		1				
47074		7				
50023		12				
	100	Each	6.0000	2.0000		

2x Sy 09/04/16

Manufactured

Rib Assembly (Basket End)

D3825-041RevA

Warehouse	Loc	c Oty	Loc Code		
Location					
Main Warehouse					
ST		6			
48668		6			
	100	Each	2.0000	2.0000	

2x St 09/07/16

Rib / Gusset Assembly

D3826-041RevB

Warehouse	Loc Qty	Loc Code	
Location	, , , , ,		
Main Warehouse			
ST	2		

48644 B 50028

Picklist Print

July 10, 2009 11:21:41 AM

Work Order ID: 50195

Parent Item:

D2221RevH

Parent Item Name: 350 Basket Base

Manufactured

No

Comments:



Start Date: 7/15/09

Required Date: 7/27/09

Page 4

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status	
D3827-041RevA		Manufactured	No			100	Each	6.0000	1.0000				

Rib Assembly (Inboard)

D3832-1RevA

Mesh (Base)

							_
Warehouse	Loc	c Qty	Loc Code				
<u>Location</u>							
Main Warehouse							
ST		6				0.1	
48454		6			1x -	SY09/04/1	14
	100	Each	5.0000	1.0000		, , , , , , , ,	,0

Warehouse	Loc Oty	Loc Code	
Location			
Main Warehouse			
ST	2		
46306	1		
46774	1 .		
Main Warehouse			
WA	3		
48645	3		_Lx

Picklist Print

July 10, 2009 11:21:41 AM

Work Order ID: 50195

Parent Item:

D2221RevH

Parent Item Name:

350 Basket Base

Comments:



Start Date: 7/15/09

Required Date: 7/27/09

Start Qty: 1.00

2.0000

Required Qty: 1.00

Component Item ID/ Item Name

Replacement Mfg/ Item ID

Purch

Manufactured

Primary Item Location

No

Location

Route Seq ID

100

Unit of Measure Hand

Each

Qty on

Remaining Otv Qty To Pick Issued

Date Issued

Status

Page 5

D3833-1RevA

Mesh (Base End Face)

Warehouse Location Loc Qty

Loc Code

5.0000

5

Main Warehouse

Last

ST

46665 48646

50005

1x -84 09/04/21

DESCRIPTION ITEM QTY P/N Æ X D2221 BASKET BASE ASSEMBLY (AS350) D2221-1 RIB 3 2 D2221-5 RIB 1 D2221-7 RIB D2232-3 BASKET HINGE 5 2 6 2 D2235-1 RIB D2581 MOUNTING BRACKET 7 2 8 2 D3442-1 SHIM 9 2 D3825-041 RIB ASSY (BASKET END) 10 2 D3826-041 RIB/GUSSET ASSY D3827-041 RIB ASSY (INBOARD) 11 1 D3833-1 MESH, BASE END FACE 12 2 13 1 D3832-1 MESH (BASE) **D2221 BASKET BASE ASSEMBLY (AS350)** (MESH SHOWN LOCALLY FOR CLARITY) REVISED PARTS LIST AND ADDED TIEM" COLUMN TO PARTS LIST (ZN D3-1). REVISED SECTIONS A-A, B-B AND C-C (ZN C6-3, C2-3 AND A6-3). REVISED DETAIL D(ZN B7-4): ADDED DETAIL IE (ZN A6-4): ADDED SECTION F-F (ZN B2-4): ADDED DWG DETAILS FOR D2221-1-15-7 (SHEET 5); TOL REVISED TO 2 DEC PLACES (ZN D8-3 AND ZN B4-3); DA825-041 REPLACES D2221-307237-3, D3826-041 REPLACES D2221-001 NIBOARD SIDE: ADDED D08332-1 AND D3833-1. REASON: SATISFY "LEAN MANUFACTURING" PROGRAM. 08.09.18 MATERIAL FOR -1, -3, -5 & -7 WAS 0.060 WALL; TOLERANCE FOR 96.00 DIM WAS +/-0.01 AND 56.00 DIM WAS REF (27 B6-2); BOZ DIM WAS "HARD" DIMENSION IS NOW "REF" (2N B4-2); NOTE 5 TRANSFERED FROM SHT 1 TO SHT 2; SHT 2 MESH MATERIAL UPDATED; DRAWING TRANSFERED TO "B" FORMAT AJS 08.06.16 ADD SHIM UNDER HINGE; ADD HOLES FOR SPLIT LID BASKET F РΗ 05.06.07 CHANGE HINGE СР 01.04.19 Ε D CHANGE LATCH BW 96.06.21 SEPARATE BASKET AND LID С ĶН 95.11.21 REV. DESCRIPTION DATE BY DESIGN **DART AEROSPACE LTD** DRAWN HAWKESBURY, ONTARIO, CANADA 2) FINISH: POWDER COAT GLOSS WHITE (4.3.5.2) PER DART QSI 005 4.3 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED DRAWING NO. CHECKED REV. H D2221 MFG. APPR. SHEET 1 OF 5 4) UNITS: INCHES UNLESS OTHERWISE NOTED 4) UNITS: INCHES UNLESS OTHERWISE NOTE: 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX 6) IDENTIFICATION: N/A 8) WEIGHT: 42.00 lbs APPROX TITLE **APPROVED** BASKET BASE ASSEMBLY (350) NTS DE APPR COPYRIGHT © 1994 BY DART AEROSPACE LTD
THIS DOCUMENT IS PRIVATE AND COMPONENTIAL AND IS SUPPLIED ON THE EXPRESS COMPONENTIAL THE NOT TO BE USED FOR ANY TREPOSE OR COMPONENTIAL THE TOWN TO THE PROPERTY OF TH DATE 9) MASK ALL HOLES PRIOR TO POWDER COATING 08.09.18

С

3

